UNCLASSIFIED

LIMITATION CHANGES

AD NUMBER AD839404

TO:

Approved for public release; distribution is unlimited.

FROM:

Distribution authorized to U.S. Gov't. agencies and their contractors; Critical Technology; 13 MAY 1968. Other requests shall be referred to Assistant Chief of Staff for Force Development (Army), Attn: FOR-OT-RD, Washington, DC 20310. This document contains export-controlled technical data.

AUTHORITY

AGO D/A ltr, 29 Apr 1980

THIS REPORT HAS BEEN DELIMITED

AND CLEARED FOR PUBLIC RELEASE

UNDER DOD DIRECTIVE 5200.20 AND

NO RESTRICTIONS ARE IMPOSED UPON

ITS USE AND DISCLOSURE.

DISTRIBUTION STATEMENT A

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED.



DEPARTMENT OF THE ARMY OFFICE OF THE ADJUTANT GENERAL WASHINGTON, D.C. 20310

IN SER V SEREE TO

AGAM-P (M) (7 Aug 68) FOR OT RD 682255

16 August 1968

SUBJECT: Operational Report - Lessons Learned, Headquarters, 520th
Transportation Battalion (AM&S)(GS), Period Ending 30 April 1968
STATEMENT #2 UNCLASSIFIED

transmittal to foreign governments or foreign mationals may be made only with prior approval of

1. Subject report is forwarded for review and evaluation in accordance with paragraph 5b, AR 525-15. Evaluations and corrective actions should be reported to ACSFOR OT RD, Operational Reports Branch, within 90 days of receipt of covering letter.

Information contained in this report is provided to insure that the army realises current benefits from lessons learned during recent operations.

3. To insure that the information provided through the Lessons Learned Program is readily available on a continuous basis, a cumulative Lessons Learned Index containing alphabetical listings of items appearing in the reports is compiled and distributed periodically. Recipients of the attached report are encouraged to recommend items from it for inclusion in the Index by completing and returning the self-addressed form provided at the end of this report.

BY ORDER OF THE SECRETARY OF THE ARMY:

1 Incl

KENNETH G. WICKHAM
Major General, USA

The Adjutant General

DISTRIBUTION:

Commanding Generals

US Continental Army Command

US Army Combat Developments Command

Commandants

US Army Command and General Staff College

US Army Air Defense School

US Army Aviation School

US Army Signal School

US Army Southeastern Signal School

US Army Transportation School

SEP 1 6 1968

1

DEPARTMENT OF THE ARMY HEADQUARTERS, 520TH TRANSPORTATION BATTALION (AM&S) (GS) APO 96289

AVGFP-O

13 May 1968

SUBJECT: Operational Report of Headquarters, 520th Transportation Battalion (AN&S) (GS), AFC 96289, for Period Ending 30 April 1968, RCS CSFCR-65 (R1)

Commanding Officer
34th General Support Group (AM&S)
APO San Francisco 96309

- 1. Under the provisions of the United States Army Vietnam Regulation 525-15, dated 13 April 1968, the following report is submitted.
- 2. Section 1, Operations: Significant Activities
- a. During the reporting period this Battalion consisted of Headquarters and Headquarters Company, 20th Transportation Company (Aircraft Direct Support), 605th Transportation Company (Aircraft Direct Support), 539th Transportation Company (General Support) and AVEL Central (Provisional). The organizational structures of the reporting organizations are contained in inclosures 1 through 4.
- b. This Battalion supported a total of 780 aircraft, made 159 field recoveries, and performed 287 maintenance extractions during the reported period.
- c. The Battalion engaged in 8 days of training and had a total of 764 persons attend various classes.
- d. During the reporting period the 20th Transportation Company moved into the new maintenance hanger, increasing the maintenance efficiency of that unit.
- e. Cn 10 April, this Battalion assumed the mission of processing inbound and outbound aircraft arriving and departing the Saigon area by air. Type of aircraft processed include OH-6, UH-1, AH-1G, CH-47, O-1, and U-6 aircraft. This mission is being accomplished by civilian augmentation and military personnel drawn from Battalion resources.
- f. No unusual problems or situations confronted the Battaltion during this reporting period which were not resolved by standard doctrine or procedures.

FOR OT RD 682255 VACLE-0

SUBJECT: Operational Report of 520th Transportation Battalion

13 May 1968 4

3. Section 2, Lessons Learned: Commander's Observations, Evaluations, and Recommendations

a. Personnel

- (1) Shortage of critical skilled personnel (MOS 67, 68, and 76 series)
- (a) Observation: Continuous rotation of personnel in critical mission support areas without sufficient replacement personnel in the pipeline to allow continuity is seriously affecting this Battalion's ability to perform its mission.
- (b) Evaluation: The units of this Battalion are continuously below strength on personnel in critical support areas. This is occurring primarily in supervisory personnel, (67, 68, 76 areas), aircraft technical inspectors (67 series), engine and airframe repair personnel (68G, 68B series), and aircraft supply personnel (76 series). This constant shortage creates turbulence and instability which affects this unit's capability to perform its technical support mission.
- (c) Recommendation: That the rotation interval of these critical skilled personnel and CONUS school output be adjusted as required to insure timely input of replacement personnel.
 - (2) Excessive amount of on-the-job training required for maintenance personnel.
- (a) Evaluation: The requirement in this Battalion to extensively train personnel on initial field assignment to aircraft maintenance units seriously detracts from the productive maintenance and supply effort. The difficulty of providing good OJT to inexperienced personnel is compounded by the lack of experienced crew leaders (senior repairmen E-5) and supervisory personnel. In the direct and general support units of this Battalion, an average of four months of OJT is required in 67 and 68 skills before the school trained mechanic can adequately perform in his MOS.
- (4) Recommendation: That maintenance personnel be given less theory in school with added emphasis being placed on practical exercise of repair functions under close supervision. Although the difficulty of accomplishing this under an accelerated training program is recoganized it would appear more desireable to have fewer skilled personnel prepared to function successfully upon assignment with other personnel requirements admittedly being filled with apprentice or helper repairmen.

AVGFP-0 13 May 1968 SUBJECT: Operational Report of 520th Transportation Battalion

- b. Operations
- (1) Lack of equipment specifically designed for aircraft recovery operations.
- (a) Observation: No standard equipment is available, through Army supply channels, for the specific use of evacuation of downed aircraft by external sling lift.
- (b) Evaluation: The use of nylon strap material for the recovery of UH-1/AH-1G aircraft has been successful to date; however, the equipment needed to evacuate fixed wing and OH-6 aircraft is not available. Attempts to evacuate fixed wing aircraft and the OH-6 helicopter with standard maintenance slings has generally been unsatisfactory. These slings and their attaching points are not sufficiently strong to withstand the stress placed when lifted and transported externally. Several aircraft have been damaged or destroyed during attempted use of standard maintenance slings.
- (c) Recommendation: That action be taken to design and develop standard equipment to be used for the field recovery and evacuation of all aircraft by external sling airlift.
 - (2) Decca Navigation Systems are not being utilized to fullest extent.
- (a) Observation: Pilots are not utilizing the Decca Navigation System in the UH-1 aircraft.
- (b) Evaluation: Due to a marked reduction in the number of maintenance requests received on Decca Navigation System components, an informal survey was conducted in order to determine the degree to which their system was being utilized. The survey disclosed that majority of the pilots were not utilizing this equipment. One of the main reasons reported was the lack of confidence on the part of the pilot that he could accurately set up the Decca equipment and interpret the resulting display.
- (c) Recommendation: That local refresher courses be conducted in the operation of the Decca Navigation Systems. This Battalion has initiated such a program utilizing the manufacturer's field representative as the primary instructor.
 - c. Training none.
 - d. Intelligence none.
 - e. Logistics
 - (1) Radio Retrofit Program
- (a) Observation: The radio retrofit program should have been accomplished in conjunction with the ZYR program.

AVGFP-0 13 May 1968 · SUBJECT: Operational Report of 520th Transportation Battalion

- (b) Evaluation: The ZYR retrofit program was started in Vietnam in 1966 to install the KY-28 voice security system. Since the beginning of this retrofit program several hundred aircraft have been modified. It was recently discovered that this modification did not render the circuit secure and another retrofit program called ZYS must be accomplished. All previously modified aircraft must once again be sent to a retrofit site for further modification.
- (c) Recommendation: That a more thorough research program be established to eliminate duplication of work and needless down time on the aircraft.
 - (2) Proper grounding of the SB-22 switchboard
- (a) Observation: The present grounding system for the SB-22 switchboard is inadequate.
- (b) Evaluation: It has been noted that, during severe electrical storms, the grounding procedures for the SB-22 switchboard, as outlined in paragraph 16, FM 11-5805-12, do not provide for safe operation.
- (c) Recommendation: That switchboard operators utilizing this switchboard exercise extreme caution when operating during electrical storms. Supervisory personnel should insure that additional grounding instructions as outlined in TM 11-676 are followed.
 - (3) Safeguarding of shipping documents and historical records.
- (a) Observation: Shipping documents and historical records are being received in an illegible and mutilated condition.
- (b) Evaluation: Many shipments of high dollar value parts and components are being recieved with accompanying documents illegible or mutilated due to damage caused by weather or rough handling. This causes further delay in handling and processing of the item for use, repair, overhaul, or other disposition. Often, items must be salvaged or overhauled because of the inability to determine historical facts.
- (c) Recommendation: That all shipping and historical documents be placed in plastic containers and firmly attached to the shipping container or secured in the specific location designed for this purpose.
 - f. Organization none.

g. Other - none.

John 7. Eggens LTC, TC

Commanding

4 Incl Withdrawn, Hqs, DA

Organizational Chart HQ & HQ Co-

-Organizational Chart 20th/605th Trans Co (ADS)

Organizational Chart 539th Trans Co (08)

Organizational Chart AVEL to Con (Prov)

ZÌ.

AVOF-B (13 May 68) lst Ind
SUBJECT: Operational Report of Headquarters, 520th Transportation
Battalion (AMS)(GS), APO 96289, for Period Ending 30 April
1968, RCS CSFOR-65 (RI)

DA, HQ, 34th General Support Group (AMAS), APO 96309, 30 May 1963

TO: Commanding General, United States Army, Vietnam, ATTN: AVMAV-DST, APO 96375

- 1. This headquarters has reviewed the CRIL of the 520th Transportation Bettalion (AMAS) for the period ending 30 April 1968 and concurs as written.
- 2. A copy of this indorsement has been provided the 520th Transportation Battalion (AMES).

FOR THE COMMINDER:

JOHN O. NORTHPINGE
MAJ, TO
Adjutant

GF: HQ, 520th Trans Bu

Franking.

AVHGC-DST (13 May 68) 2d Ind MAJ Thompson/dls/LBN 4485 SUBJECT: Operational Report of Headquarters, 520th Transportation Battalion (AMAS) (QS), APO 96289, for Period Ending 30 April 1968, RCS CSPCS-65 (R1)

HEADQUARTERS, US ARMY VIETNAM, APO San Francisco 96375 7 JUN 1968

TO: Commander in Chief, United States Army, Pacific, ATTN: GPOP-DT, APO 96558

- 1. This headquarters has reviewed the Operational Report-Lessons Learned for the quarterly period ending 30 April 1968 from Headquarters, 520th Transportation Battalion (AMAS) (GS) as indorsed.
- 2. Concur with report as submitted.

FOR THE CONMANDER:

JOHN V. GETCHELL Captain, AGC Assistant Adjutant General

Re Globell

Oy furn: HQ 520th Trans Bn (AMAS) (GS) HQ 34th General Support Group (AMAS) GPOP-DT 13 May 68) 3d Ind

SUBJECT: Operational.Report of HQ, 520th Trans Bn (AM&S)(GS) for Period Ending 30 April 1968, RCS CSFOR-65 (R1)

- HQ, US Army, Pacific, APO San Francisco 96558 24 JUL 1968
- TO: Assistant Chief of Staff for Force Development, Department of the Army, Washington, D. C. 20310
- 1. This headquarters has evaluated subject report and forwarding indorsements and concurs in the report as indorsed.
- 2. Reference (page 3) paragraph 3b(1): Standard equipment for evacuation of aircraft by means of external sling lift is available in applicable technical manuals. Normal requisitioning procedures IAW AR 735-35 should be used to obtain the required equipment and materials.
- b. For methods of aircraft recovery in general, TM 55-413, "Recovery and Evacuation of Army Aircraft," should be used in conjunction with the current aircraft maintenance manuals.
- c. Failure or deficiencies in standard equipment used during the recovery and evacuation of aircraft should be submitted by Equipment Improvement Recommendation (EIR). The failure or inadequacy of the equipment is sufficient grounds for the submission of an EIR whether the aircraft being evacuated has been damaged or not.
- d. When methods of recovery and evacuation developed by units differ with the current published manuals and are considered to be superior, then a DA 2028 (Recommended Change to DA Publications) should be submitted recommending that the manuals be changed.
- 3. Reference (page 3) paragraph 3b(2): It appears that the Decca Mavigation System may have outlived its usefulness. While one of the reasons for this lack of use may be as stated in referenced paragraph, it appears that another reason may be a lack of need for the equipment. Since the Decca System was installed in Vietnam, many improvements have been made in other navigation facilities. There is now much more complete coverage of the operational areas by ADF, VOR, TACAN, and Radar. This headquarters has no information on technical difficulties being encountered with the Decca System; however, the subject will receive

10

2 4 JUL 1968

GPOP-DT (13 May 68) 3d Ind SUBJECT: Operational Report of HQ, 520th Trans Bn (AM&S)(GS) for Period Ending 30 April 68, RCS CSFOR-65 (R1)

staff enquiry in the future. Evaluation by the using units is desired in the preparation of appropriate EIR or recommendations for elimination of the equipment.

FOR THE COMMANDER IN CHIEF:

Chilant/

C.L. SHORTT CPT, AGC Asst AG

Cy furn:

	DOCUMENT CO				
(Society classification	et title, hedy of abuttact and index	ing amounton mus		e averall report t	
•		Unclassi			
UNCSPUR, DA, Wal	hington, D.C. 20310		Ib. GROUP		
perational Report	- Lessons Learned, Hq	, 520th Tran	nsportation E	attalion (v) .
ESERIPTIVE HOTES (Type	of report and inclusive dates)		1	Feb - 30 A	n= 68
lxperiences of uni UTHOR(8) (Piro) nome, midd	t engaged ir. counters	Dentsency o	perations.	140 - 30 K	PF 00 .
	ation Battalion (AM&S)	/			•••
EPORY BAYE	13 May 1968	74. 70TAL N	IO. OF PAGES	76. NO. OF R	270
SHYRAEY OR SAAHY NO.			TOR'S REPORT NU	MOER(8)	
PROJECT NO.	15	682	2255		
N/A		98. 07HER	CPORT HOISI (Any	other numbers the	it may be easign
ISTAIGUTION STATEMENT		<u> </u>			
,	•	•			
			•		
UPPLEMENTARY NOTES		110, 400,000	ING MILITARY ACT	1 W 1 W 1	
N/A	•	OACSFOR	, DA, Washin	ston, D.C.	20310 ·
BIVALEY					
	•				
					•
		۵			
		9			
		9			
		9			
		9			
		9			
		9			
		9			

UNCLASSIFIED Recurity Classification

DD . ***.. 1473

The fol Index:	lowing items are recommended for inclusion in the Lessons Learned
ITEM 1	
* SUB	JECT TITLE
	OT RD #
***PAG	
ITEM 2	
SUB	JECT TITLE
	OT RD #
PAG	
ITEM 3	
	JECT TITLE
FOR	OT RD #
PAG	E #
ITEM 4	
SUB	JECT TITLE
	OT RD #
PAG	
ITEM 5	
SUB	JECT TITLE
	OT RD #
PAG	
* Subject of interest	ect Title: A short (one sentence or phrase) description of the it
	OT RD $\#$: Appears in the Reply Reference line of the Letter of This number must be accurately stated.

***Page # : That page on which the item of interest is located.

DEPARTMENT OF THE ARMY

POSTAGE AND PEES PAID DEPARTMENT OF THE ARMY

OACSFOR Washington, D.C. 20310

OFFICIAL BUSINESS

Office of the Assistant Chief of Staff for Force Development ATTN: Operational Reports Branch Headquarters, Deaprtment of the Army Washington, D.C. 20310

NA Tabel 18, 1 And 10 - SOFTWOLK PRIVIOUS OF THIS LAST ASSOCIATE

10—70013-1

- -FOLD - -

STATE